

No.60/Advice/CFO/MD/2013

To

✓ The Headmistress,
St. Mary's English High School,
6th Cross, Balaji Layout,
Kannarpady,
Udupi – 576 103.

Sir,

Sub: Fire prevention, fire fighting and evacuation measures in already constructed & functioning School building at Sy.No.60/3A etc., 69 Moodanidamboor Village, Udupi Taluk and District.

Ref: 1. Report No.80/Buld./DFO/Udupi/2013(11) dated 27-06-2013.

2. Standing Order No.151 dated 11-01-2011.

>>>><<<<

The District Fire Officer, Udupi has inspected St. Mary's English High School building constructed at Sy.No.60/3A etc., 69 Moodanidamboor Village, Udupi Taluk and District on 27-06-2013. The school building was inspected from fire prevention, fire fighting and evacuation point of view. The details of the report and suggestions are as follows:-

A. The details of the premises.

1. Address of the premises

- St. Mary's English High School,
6th Cross, Balaji Layout,
Kannarpady,
Udupi – 576 103.

2. Number of buildings

- One.

3. Number of floors

- Ground floor and one upper floor.

4. Floor wise details of occupancy

Ground floor

- 8 Nos. class room, 1 No. sports room, 1 No. counseling room, 1 No. staff room, 2 Nos. Activity room, 1 No. computer lab, 1 No. Head Master room, 1 No. Correspondent room, 1 No. office room and services.

First floor

- 1 No. prayer room, 1 No. Library, 2 Nos. Laboratory, 12 Nos. class room, 1 No. Music room, 1 No. staff room 1 No. Activity room & services

